S E C R E 162207Z

- CAMERA B 12 WAS USED IN MISSION 3229 FLOWN ON 8 OCTOBERS COT 17  $C_0$ 1. 1963: PROCESSING WAS ACCOMPLISHED BY EASTMAN KODAK.
  - 2. ORIGINAL NEGATIVE:

A. THE RESOLUTION IS GOOD ALTHOUGH THE FILM WAS UNDER-EXPOSED.

17 OCT 1963

HFS

CJS

PRS

Grace (File)

- 9L SIDE: THIS WAS THE FIRST OPERATIONAL MISSION В. UTILIZING TYPE 4400 (SO 130) FILM. BASED ON AVAILABLE INFORMATION FOR THE CONTROL OF THE CONTROL CONCERNING THE CAMERA/EMULSION/EXPOSURE COMBINATION IT WAS DECIDED TO PROCESS AT FULL DEVELOPMENT. WHEN IT WAS DISCOVERED 1 THAT THE DENSITY WAS INADEQUATE IT WAS DECIDED TO FORCE PROCESS WARM DEVELOPER) ON THE 9R. IT MUST BE NOTED THAT THIS WAS A SHORT MISSION - ONLY 61 FRAMES ON EACH SIDE.
- C. 9R SIDE: AS A RESULT OF THE AFOREMENTIONED PROCESSING CHANGE THE DENSITY OF THIS SIDE ON THE MISSION WAS GREATLY IM-PROVED. THE CONTRAST AND GROSS FOG, HOWEVER, WERE ADVERSELY AFFECTED.
- D. THE MISSION WAS TERMINATED AFTER 61 FRAMES DUE TO A CAMERA MALFUNCTION, WHICH WAS LATER DETERMINED TO HAVE BEEN Declassification Review by NGA/DoD SHORT IN A CAMERA DIODE. THERE WERE NO MAJOR PROCESSING
  - 3. POSITIVE:

MALFUNCTIONS.

A. PI SUITABILITY IS FAIR ON THE 9L SIDE WITH A DEFINITE DEGRADATION IN THE SHADOWS. PI SUITABILITY ON THE 9R SIDE

IS FAIR TO GOOD WITH SOME LOSS OF IMAGERY IN THE SHADOWS AND A TENDENCY TOWARD IMAGE BLEEDING IN AREAS OF HIGH CONTRAST.

B. PRINTING AND PROCESSING WERE GOOD.
SECRET

END OF MESSAGE